



# STATUS OF WATER BODIES



## DISTRICT - EAST

S. No.	G. No.	Distt. S.no	Name of Village's No. of Water Bodies/pond's	Land owner ships	Khasra No./Areas	Lat/Long	Years & Dates of Inspection	Site position/Directions/Opinions	Status								Action Plan	Photograph of the Water Body	
									Fully, Partially, Under	Dry	Wet (Seasonal &	Sewage	General Encroachment	Built up (Legal/Illegal)	Non Treceable	River Belt			
1	12	12	Ghazipur F/74(4) (1) Bus Stand (2) Ench villagers (3) Alloted to Delhi agricultute marketing board (1 to 3 allotted by BDO)	MCD	(d)464(0-09)	77°19'14.17"E/ 28°38'6.18"N	27.06.2012 01.06.2015	To develop MCD park. Park at site. Kh. No. 464 is under the Jurisdiction of MCD. To be developed by MCD. To clean from gargabe. Planting around. To be used as Green Belt. Area to be procted by plantation. On 4.2.2007, the Committee visited the water body situated near NH 24 in the presence of DDA officials. The in its list has whon the water body as 15000 sq mts however now the DDA officials took the Committee in village stating that the water body is situated in the village. Complete dry. It is in ruined state. A park was to be devleoped on this water body by MCD. DDA & Revenue present but MCD officers not present. Court Commissioner directed revenue officers and Nodal Officer - Water Bodies to take up this matter with commissioner EDMC.	Under developed	Permanent Dry								To clean from gargabe. Planting around. To be used as Green Belt. Area to be procted by plantation.	

2	29	29	Mandawali fazilpur	MCD	MCD (a)625, 626 (30-0)	28° 37' 47.439" N 77° 17' 45.070" E	03.06.2009 06.06.2012 27.06.2012 01.06.2015	<b>more and more trees species to be planted and Rain water harvesting system to be developed.</b> Plan constructed by MCD. One side there is encroachment and other side garbage dumping. School exists on one side. Surrounded by boundary wall. This water body had been transferred by DDA to MCD for development of a park and where a community hall had been proposed. This is totally illegal. The water body should be restored.						Heavily Legally Built up			To remove garbage dumping and encroachment. More and more trees species to be planted and Rain water harvesting system to be developed.	
3	47	47	Vinod Nagar (3)	MCD	(b)34000 sq. mtrs. K No. 625 MCD Park	28° 37' 46.310" N 77° 17' 44.058" E	04.02.2007	<b>G.No. 29 and 47 are same.</b> Rain water harvesting has been proposed. A park has been developed by MCD long back. Further action is to be taken by the MCD. Rain water harvesting. This water body admeasuring about 34000 sq. mtrs. Falls within the Vinod Nagar West Colony near Senior Secondary School. It has been developed as a park by MCD.	Under developed	Dry						Rain water harvesting has been proposed.		



DISTRICT- NORTH WEST



DISTRICT- NORTH WEST																		
S. No.	G. No.	S. No	Name of Village's No. of Water Bodies/ Pond's	Land owners	Khasra No/Areas	Lat/Long	Date of Visit	Remarks	Status							Action Plan	Photograph of the Water Body	
									Fully, Partially, Under Developed	Dry	Wet (Seasonal & Permanent)	Sewage	General Encroachment	Built up (Legal/Illegal)	Non Treceable			River Belt
11	292	34	Chaukri mubarikbad F/74	MCD	519(22-9)	28° 40' 27.319" N 77° 10' 18.640" E	23.12.2008 24.12.2008 05.06.2012	<b>Rain Water Harvesting and plantation to be done.</b> No water body but houses exists on the site. Detail report along with photographs from EE concerned annexed. Fully Encroached. If there is a Court Case, report to CC. Water body being developed at site. Minimum concretization. Narrower pathways, more greenery and rainwater access be ensured.	Under Developed	Dry			Fully Encroached				Rain water harvesting and plantation to be done.	
12	415	157	Samay pur F/89	MCD	(a)13/26(4-16)	28° 44' 55.635" N 77° 8' 43.102" E	24.12.2009 30.12.2009 09.02.2013	<b>This land is Gram Sabha land and placed at the disposal of DDA vide notification No. F.9 (4)/89-L&amp;B dt. 5.10.89 and the disposal of DDA. But the physical position of the above said land has not been handed over to DDA by BDO till date.</b> There exists a park now at the site, known as Krishan Vatika. Park.	Developed	Dry								
13	419	161	Sakur pur F/74	MCD	(b)30//27(1-1)	28° 40' 58.236" N 77° 8' 27.224" E	07.05.2011	<b>Pertains to DDA. The site inspected by field staff and on local enquiry , it came to know that there existed a talab near the site of Community Hall. The land at present is encroached by rickshaw walas and Kabarīs etc. The land, however, belongs to DDA.</b> Plantation and water harvesting system is required. Community Centre exists in Khasra no. 30/27 constructed by <b>MCD</b> . Authorities were directed to take action against encroachers on the water body land. Park.					Legally Built up			Plantation and water harvesting system is required.		

**DISTRICT-SOUTH**


S. No.	G. No.	S.No.	Name of village's No of Water Bodies/Pond's	Water owing agency	Khasra No.	Lat/Long	Date of Inspection	Site/position/Directions/opinions	Status							Action Plan	Photograph of the Water Body	
									Fully, Partially, Under Developed	Dry	Wet (Seasonal & Permanent)	Sewage	General Encroachmen	Built up(Legal/Illeg	Non Treceable			River Belt
452	14	28		MCD	(d) 82(8-8) New water body	28° 29' 20.608" N 77° 11' 12.992" E	26.03.2010 23.04.2011	<b>Rain Water Harvesting to be done.</b> Land allotted to MCD, and park has been developed by MCD, Water Harvesting System DJB has to be done. Report regarding soil dumping at the site by Tehsildar, more plantation is required court comm., directed the Horticulture unit of MCD to demarcate the land. Park exists. To be checked by BDO. No record was available, demarcation to be carried out and submit report to the court committee and develop it as water body.	Under Developed	Dry							Rain water harvesting to be done.	
523	15	99	Saidulajab	MCD	(a)200/2(1-13)	28° 31' 2.847" N 77° 12' 8.709" E	24.12.2010	<b>Adjoining to Distt. Office.</b> Encroachment was found to exists at site. The authorities i.e. <b>DDA</b> & Revenue staff were directed to carry out demarcation and remove the encroachment and water body to be handed over to developing agency.	Under Developed	Dry			Encroachment				To remove encroachment.	



**DISTRICT-SOUTH WEST**


S. No.	G. No.	S. Nos.	Name of village's No of Water Bodies/Pond's	Land ownership	Khasra No.	Lat/Long	Date of Visit	Remarks	Status							Action Plan	Photograph of the Water Body	
									Fully, Partially, Under Developed	Dry	Wet (Seasonal & Permanent)	Sewage	General Encroachment	Built up (Legal/Illegal)	Untreaceable			River Belt
17	588	5	Bharthal	MCD	184(15-18)	28° 32' 30.428" N 77° 2' 41.163" E	03.09.2011 26.12.2011 19.01.20130 9.06.2016	Inspection to be done. Looks like a stadium as stairs developed on the boundary. Catchment not developed.	Under Developed		Seasonal Wet		Partly Encroached by way of temple					
18	591	8		MCD	184(19-04)	28° 32' 31.246" N 77° 2' 40.078" E	03.09.20110 2.04.2012	Inspection to be done. Surrounded by boundary wall. Water is available in lower portion. Steps are built to go down. Most of the land of water body is vacant. Plantation and catchment to be developed by MCD since it pertains to MCD. One side temple. MCD is responsible for not developing the water body.	Under Developed		Seasonal Wet		Partly Encroached				Plantation and catchment to be developed	
19	615	32	Matiala F/02	MCD	8/7(4-16)	28° 37' 4.048" N 77° 2' 52.610" E		Rain Water Harvesting to be done. Park developed by MCD . Need rain water harvesting system.	Developed								Rain water harvesting to be done.	
20	616	33		MCD	22/29(9-17)	28° 36' 43.870" N 77° 2' 48.243" E		Park developed by MCD.MCD to develop water harvesting system, has community Hall	Under Developed		Seasonal Wet						Water harvesting system to be developed.	
21	617	34		MCD	not given	77° 2'27.22"E / 28°36'54.82"N	4.4.2009 7.6.2010	Water body developed by DSIIDC. DDA was directed to stop the village sewage water flowing into it.	Developed		Seasonal Wet							
22	618	35		MCD	22/26(06-12)	28° 36' 48.888" N 77° 2' 37.777" E	4.4.2009	Recharge pits installed ,plantation is needed.	Under Developed		Seasonal Wet	Sewage flow					Plantation to be done.	

23

701	118	Qajipur	MCD	42(5-6)		4.6.2012	Under Developed. Dry. Govt. School exists. Needs plantation.							Legally Built up			Plantation to be done.	
-----	-----	---------	-----	---------	--	----------	---	--	--	--	--	--	--	------------------	--	--	------------------------	---




**DISTRICT - WEST**


S. No.	G. No.	S. No.	Name of Village's No. of Water Bodies/Pond's	Land owner ships	Khasra No/Areas	Lat/Long	Years & Dates of Inspection	Site position/Directions/opinions	Status							Action Plan	Photograph of the Water Body
									Fully, Partially, Under Developed	Dry	Wet (Seasonal & Permanent)	Sewage	General Encroachment	Built up(Legal/Illeg)	Untreaceable		
24	862	13	Baprola	MCD	(b)1530(44-17)	28° 39' 13.820" N 77° 7' 53.120" E	07.05.2011 07.06.2012	No water body exists at the site. Heavily built up and unauthorized. MCD school, educational office, houses, shops and temple are there to be handed over to <b>DDA</b> .						Illegally Heavy Built up			
25	867	18	Garhi peeran F/89 @ Peeragarhi	MCD	Paschim Vihar, 14700 Sq.mtrs.	28° 40' 19.386" N 77° 5' 43.872" E	02.04.2011	DDA has developed the land in the name of Pachim Vihar District Park. DDA was directed to provide catchment area from the road for inflow of water in the park as the same is below the road.	Developed	Dry							
26	881	32	Keshopur F/74	MCD	302 OLD 35 NEW(5-18)	28° 38' 46.997" N 77° 4' 44.280" E	03.09.2011 07.06.2012	Park exists there. It should be maintained as green.									
27	893	44	Mundka	MCD	(f)370min(4-16)	28° 40' 48.877" N 77° 1' 34.800" E	27.03.2010	Rain Water Harvesting. No water body is visible at the park site. Park exists at site. Water harvesting is the best option as the area is low lying area. The said park is maintained by MCD.	Developed	Dry						Rain water harvesting to be done.	
28	897	48	Nangloi jat	MCD	(b)34/17/1(1-10)	28° 40' 54.281" N 77° 3' 45.976" E	27.03.2010	Rain Water Harvesting. Land developed in the shape of park. Dry. MCD Park exists. The site is known as Nirmal Park in Nangloi Extension. This is low lying area to be used for rain water harvesting by I&FC.	Developed	Dry		Sewage flow				Rain water harvesting to be done.	
29	898	49		MCD	(c)61/4/3(1-5)	28° 40' 30.405" N 77° 3' 57.195" E	09.06.2008	Sewage flow. The Community Hall existing is not in the water body but adjoining to it. Storm water delinked form going into the water body and now, only Rain water is coming into it. Detailed report of field staff annexed. MCD Community Centre. Work is in progress. The area is free from encroachment. Authorities were directed to stop the dirty water coming from nearby colony.				Sewage flow		Legally Built up			



**DISTRICT-NEW DELHI**

S. No.	G. No.	S. Nos.	Name of village's No of Water Bodies/Pond's	Land ownership	Khasra No.	Lat/Long	Date of Visit	Remarks	Status							Action Plan	Photograph of the Water Body
									Fully, Partially, Under Developed	Dry	Wet (Seasonal &	Sewage	General Encroachment	Built up(Legal/Illeg	Untreaceable		
31	940	16	Mohd. Pur murirka F/66	MCD	823/12(8-7)	28° 33' 9.526" N 77° 10' 18.439" E	4.12.2010	<b>MCD Park.</b> On the demand of the villagers of Munirka and surrounding DDA areas this whole area has been developed in to a sports complex and was inaugrated by the then Dy. Prime Minsiter of India Sh. L. K. Advani in Dec. 2002. Land is being used for the sports facilities by the villagers. During rain it acts as a water harvesting point which is basic point of the water body. Park developed by MCD, encroachment.						Legally Built up			
32	979	55	Samalkha	MCD	51(10-7)	28° 32' 7.949" N 77° 5' 14.822" E	10.06.2016	Johar	Develope d						TRACED		

**DISTRICT-CENTRAL**

S. No.	G. No.	S. Nos.	Name of village's No of Water Bodies/Pond's	Land ownership	Khasra No.	Lat/Long	Date of Visit	Remarks	Status							Action Plan	Photograph of the Water Body	
									Fully, Partially, Under Developed	Dry	Wet (Seasonal & Permanent)	Sewage	General Encroachment	Built up (Legal/Illegal)	Untreaceable			River Belt
33	1001	15	Nimari F/74	MCD		28° 39' 11.725" N 77° 10' 42.057" E		No water body as per revenue record of GNCTD, Delhi, which is provided by the SDM (MT) and Civil Line exists in these Revenue Estates. Built up. Park.						Legally Built up.				
34	1006	20	Naini Lake	MCD	24339 Sq. mtr.	77° 11' 49.347" E	07.06.2012	<b>Model Town, Civil Line Zone. Fully Developed, Permanent Wet. Facility for boating also provided. Run by Delhi Tourism.</b>	Developed		Permanent Wet							

**DISTRICT- NORTH EAST**

S. No.	G. No.	S.No	Name of Village's No of Water Bodies/Pond's	Land owner ships	Khasra No/Areas	Lat/Long	Years & Dates of Inspection	Site position/Directions/opinions	Status							Action Plan	Photograph of the Water Body	
									Fully, Partially, Under Developed	Dry	Wet (Seasonal & Permanent)	Sewage	General Encroachment	Built up(Legal/Illegal)	Non Treceable			River Belt
4	87	34	Maujpur F/74 (3)	MCD	772/73 min (0-12)	28° 41' 28.673" N 77° 16' 21.621" E	27.08.2011	Park developed by MCD and electric Transformer exist at site. Pertain to MCD.	Developed	Dry								
5	88	35		MCD	773/773 (0-2)		27.08.2011	MCD park exists along the boundary wall. Electric transformer exists on the water body land.	Developed	Dry								
6	89	36		MCD	774/73 min (1-3)		28° 41' 28.123" N 77° 16' 21.672" E	27.08.2011	MCD park exists along the boundary wall. Electric transformer exists on the water body land.	Developed	Dry							
7	96	43	Seelam pur F/74(3) (1) DP-BDO	MCD	32 acre	28° 40' 16.170" N 77° 16' 16.753" E	03.06.2009	32 acre in which 16 acre there is a water and 16 acre there is a park. No Sewage. Submit plan for developing the water body. The water body is looked after by MCD. This is a very large time water body which mainly remains dry except during monsoons. Although efforts have been made to restore it yet on one side due to the settlement outside the water body, the boundary wall has been broken. It should be repaired. It was suggested that the time area be afforested so that people do not rake it to be a garbage pit. This should help in maintaining the water body.	Under developed		Seasonal Wet							