



DISTIC-SOUTH-WEST(List of Water Bodies in Urbanized/Rural villages)

DISTRICT-NEW DELHI

G. No.	S. Nos.	Name of village's No of Water Bodies/Pond's	Land ownership	Khasra No.	Date of Visit	Remarks	Status							Photograph of the Water Body	
							Fully, Partially, Under Developed	Dry	Wet (Seasonal & Permanent)	Sewage	General Encroachment	BUILT up (Legal/Illegal)	Untreceable		River Belt
87	1	Ghitorni	BDO	437 (17-19)	29.09.2012	Developed. Wet. Needs plantation. Work completed. It is BDO's Water body surrounded by boundary wall. Dirty water and sewage flowing is there. MCD was required to take action for cleaning the water body which has been converted into dumping yard. Needs plantation.	Developed		Wet	Sewage flow					
88	2	Malikpur Kohi	BDO	(c) 71 (5-1)	04.06.2012	Encroached. one side, suction pump is installed by I&FC Deptt. It is encroached by villagers. Court Commissioner directed the revenue & BDO staff to demarcate the water body land of Kh. No. 58 & 71 on 25.05.2012 in the presence of committee.	Under Developed		Wet	Sewage flow	Encroachment				
89	3		BDO	(d) 58(19-1)	04.06.2012	Wet. Dirty water. Encroachment and the pond is receiving discharge of entire adjoining village Abadi. Work shall be taken up after sewerage is completed by Delhi Jal Board. Natural Water body. It is full of water. Sewage flowing in water body. It is partly encroached on one side. Water body belongs to BDO.	Under Developed		Wet	Sewage flow	Fully Encroached				